



CO-OPERATIVE ELECTRIC SUPPLY SOCIETY LIMITED,

Regd. No.748/TD

A Project Financed by REC Ltd.,

New Delhi, (A Govt. of India concerned)

SIRCILLA – 505 301

Dist: RajannaSircilla

Telangana

COMPLAINT NO: 03

Applicant Name: PV Subba Reddy.

Subject:- Submission of Objections/Suggestion on O.P. Nos.70&72 of 2025;O.P.Nos 21&22 of 2025 of TGSPDCL ARR Filings.

Subject	Explanation
<p>I herewith file the Objections/Suggestions regarding the above.</p> <ol style="list-style-type: none">1) The Revenue gap of Rs 471 cr is shown as GOTS subsidy for which is not substantiated.2) The CESS details of cost of purchase from NPDCL Market rates is to be provided.3) Compliances of Directives of Hon Commission not furnished.4) DSM measures, Safety measured details to be provided.	<ol style="list-style-type: none">1) CESS Ltd., Sircilla has duly assessed and arrived at the gap. CESS Ltd., Sircilla humbly request Government of Telangana to fulfill the requested revenue gap. CESS Ltd., Sircilla shall abide by the directions of the Hon`ble Commission with regard to revenue gap. CESS Ltd., Sircilla is continuously striving to reduce the gap every year, by continuous power purchase optimization, improving internal efficiency and shall continue to do so.2) The CESS Ltd., Sircilla is purchasing power from TGNPDCL at Rs.4.77 per Unit as per Tariff order approved by the Hon`ble TGERC for the F.Y.2025-26.3) Status of Implementation of Directives is already furnished as part of ARR Filings the Hon`ble Commission.4) Further, most of the overloaded 11kV feeders are having 600kVAR line capacitor banks to support local reactive power requirements and to improve voltage profile even at tail end.. <p>Further it is to inform that in CESS Ltd., Sircilla, New AGL services are releasing duly following the DSM measures in which ISI pumset is mandatory.</p> <p>CESS Ltd., Sircilla rectified the following line defects during FY2025-26 mainly in rural areas and in agriculture fields</p> <ol style="list-style-type: none">a. 1768 Nos middle poles are erected for loose lines rectification.b. 2206 nos new poles erected in place of damaged/rusted and fell down due to heavy gale and windc. 18 DTR structures were rectified



CO-OPERATIVE ELECTRIC SUPPLY SOCIETY LIMITED,

Regd. No.748/TD
A Project Financed by REC Ltd.,
New Delhi, (A Govt. of India concerned)

SIRCILLA – 505 301
Dist: RajannaSircilla
Telangana

COMPLAINT NO: 03

Applicant Name: PV Subba Reddy.

Subject:- Submission of Objections/Suggestion on O.P. Nos.70&72 of 2025;O.P.Nos 21&22 of 2025 of TGSPDCL ARR Fillings.

<p>5) The details of case wise accidents and detailed causes shall be furnished.</p> <p>I request you to consider this submission and permit me to present further details the public hearing.</p>	<p>Sircilla, New AGL services are releasing duly following the DSM measures in which ISI pumset is mandatory.</p> <p>CESS Ltd., Sircilla rectified the following line defects during FY2025-26 mainly in rural areas and in agriculture fields</p> <ol style="list-style-type: none">1768 Nos middle poles are erected for loose lines rectification.2206 nos new poles erected in place of damaged/rusted and fell down due to heavy gale and wind18 DTR structures were rectified13 nos DTR plinth height raised396 DTR earthing renovated. <p>5)CESS Ltd., Sircilla submit that the details of accidents, along with cause wise reasons, are enclosed here with.</p>
--	---


Managing Director,
CESS Ltd., Sircilla.

2025; O.P.Nos 21&22 of

d. 13 nos DTR plinth height raised
 e. 396 DTR earthing renovated.
 5)CESS Ltd., Siricilla submit that the details of accidents, along with cause wise reasons, are enclosed here with.

wise accidents and
 will be furnished.

Sanction Amount	Reason	Cheque no./Date
5,00,000.00	insulation failure of the service wire near agri motor	524789,90/21.09.2024
5,00,000.00	came in contact with GI wire while due to damaged insulation cable	524796,97/ 21.09.2024
5,00,000.00	damaged insulation of service wire	889517,18/ 04.06.2025
80,000.00	LT line of the SS-V/100 KVA DTR was fallen to ground due to poles damage by gale & wind	524769/ 13.09.2024
40,000.00	due to earthing of phase wire to the pole in rainy condition	524767/ 13.09.2024
14,000.00	touching of LT phase wire which was cut heavy gale and rainy condition	524768/ 13.09.2024
14,000.00	11 KV line which is having less clearance from the ground	524774/ 13.09.2024
5,00,000.00	touched the tapped J wire from nearby 11 KV line by unknown person to hunt the wild animals	524894,95/ 22.10.2024
	went to the power transformer for put fuse	525087,88/07.01.2025

STATEMENT SHOWING THE FATAL ACCIDENTS IN F.Y. 2024-25.

Date of Accident	Village	Mandal/Operation section	Details of Victim (Human/Animal)	Sanction No. & Date	Sanction Amount	Reason	Cheque no./Date
27.10.2022	Anthagiri	Ellanthakunta	Sri.Oggari Mahesh S/o Yellaiah	01/26.07.2024	5,00,000.00	insulation failure of the service wire near agri motor	524789,90/21.09.2024
03.03.2024	Ellanthakunta	Ellanthakunta	Sri.Rangu Ramesh S/o Kankaiah	02/26.07.2024	5,00,000.00	came in contact with GI wire while due to damaged insulation cable	524796,97/ 21.09.2024
09.02.2024	Srigadha	Gambhiraopet	Sri.Bandela Rajaiah S/o Yellaiah	03/31.08.2024	5,00,000.00	damaged insulation of service wire	889517,18/ 04.06.2025
14.07.2024	Lingampet	Chandurthy	2 No.Cows belongs to Sri.Tharre Laxman S/o Kashaiah	04/31.08.2024	80,000.00	LT line of the SS-V/100 KVA DTR was fallen to ground due to poles damage by gale & wind	524769/ 13.09.2024
18.05.2024	Gudem	Musthabad	1 No.Buffalo Belongs to Sri.Gangamadhri Sathaiah S/o Rajaiah	05/31.08.2024	40,000.00	due to earthing of phase wire to the pole in rainy condition	524767/ 13.09.2024
16.05.2024	Musthabad	Musthabad	2 No.Sheeps belongs to Sri.Chevula Gopaiah S/o Mallaiah	06/31.08.2024	14,000.00	touching of LT phase wire which was cut heavy gale and rainy condition	524768/ 13.09.2024
26.07.2024	Vilasagar	Boinpally	2 No.Sheeps belongs to Sri.Pole Mallaiah S/o Agaiah	07/13.09.2024	14,000.00	11 KV line which is having less clearance from the ground	524774/ 13.09.2024
06.04.2023	Jai Sevalal Bhukya Reddy Thanda	Konaraopet	Sri.Bhukya Kishore S/o Balu	08/07.10.2024	5,00,000.00	touched the tapped J wire from nearby 11 KV line by unknown person to hunt the wild animals	524894,95/ 22.10.2024
08.03.2024	Kondapur	Musthabad	Sri.Chiguru Yadaiah S/o Rajaiah	09/14.11.2024	5,00,000.00	went to the power transformer for put fuse wire	525087,88/07.01.2025
10.03.2024	Bavusaipet	Konaraopet	Sri.Pambala Bhoomaiah S/o Rajaram	10/14.11.2024	5,00,000.00	lifted the iron pipes which came into contact with the 11 KV line	889412,13/13.05.2025
11.12.2022	Boppapur	Yellareddypet	Smt.Bestha Neelavva W/o Narsaiah	11/14.11.2024	5,00,000.00	due to damaged service cable of the water heater	525320,21/07.04.2025
09.01.2024	Thadur	Thangallapally	Smt.Mallaboina Madhupriya W/o Rakesh	12/10.12.2024	5,00,000.00	came in contact the cut hanging GI wire	525062&63/ 21.09.2024

	Date of Accident	Village	Mandal/Operation section	Details of Victim (Human/Animal)	Sanction No. & Date	Sanction Amount	Reason	Cheque no./Date
13	04.09.2024	Avunoor	Musthabad	11 No.Sheeps, & 2 No.Goats belongs to Sri.Bathula Mallesham S/o Raiaiah	13/17.12.2024	91,000.00	iron shed was electrically charged by damaged service wire	525070/ 28.12.2024
14	23.02.2024	Gannevanipally	Musthabad	Sri.Nimmala Prabhakar S/o Lingaiah	14/17.12.2024	5,00,000.00	damaged service wire in contact with stay wire	889273,74/25.04.2025
15	06.02.2023	Nagampet	Gambhiraopet	Sri.Chepyala Babaiah S/o Pochaiah	15/17.12.2024	5,00,000.00	phase wire of motor starter touched the rod he was carrying	889519,20/04.06.2025
16	17.08.2025	Repaka	Ellanthakunta	Sri.Moguloji Rangaiah S/o Lachaiah	16/10.03.2025	5,00,000.00	support stay wire is not insulated with the guy insulator	525275,76/15.03.2025
17	06.06.2024	Marthanpet	Konaraopet	Sri.Mundrai Sandeep Kumar S/o Vijaykumar	17/10.03.2025	5,00,000.00	shock from the pump set starter while giving supply to then service wire	not issued
18	23.11.2023	Gambhiraopet	Gambhiraopet	1No. Buffalo belongs to Smt.Agadeni Laxmi W/o Ramulu	18/10.03.2025	40,000.00	earth pipe present adjacent to the pond of water may have caused electrical induction	525274/ 15.03.2025
					Grand Total	62,79,000.00		

Bonegoldbe

Managing Director
CESS LTD.,SIRCILLA

STATEMENT SHOWING THE FATAL ACCIDENTS SANCTIONS IN F.Y. 2025-26.

No.	Sanction No. & Date	Date of Accident	Village	Mandal/Operation section	Details of Victim (Human/Animal)	Sanction Amount in Rs.	Reason	cheque no./Date
1	01/22.05.2025	20.10.2023	Bhukya Thanda	Veernapally	1 No.Cow Belongs to Sri.Guguloth Shivaram S/o Kistu	40,000.00	electrocuted due to contact of cow with insulation less service wire	889511/ 04.06.2025
2	02/22.05.2025	28.12.2024	Yellareddypet	Yellareddypet	Sri.Adla Raja Narsaiah S/o Narsaiah	5,00,000.00	joint between starter to borewell has no insulation was dropped into the water led to the electrocution	889509,10/ 09.07.2025
3	03/20.08.2025	12.06.2025	Korem	Boinpally	1 No.Buffalo belongs to Sri.Romala Anjaiah S/o Hanmaiah	40,000.00	LT three phase AGL line snapped and fell into adjacent stored rain water, got electrocuted	889733/ 23.08.2025
4	04/09.10.2025	22.05.2025	Venkatapur	Yellareddypet-I	1 No.Goat belongs to Sri.Pandavula Nagesh S/o Venkati	7,000.00	came into contact with SS-XIV 100/100 KVA Iron DP failed guy insulator stay wire	889850/ 10.10.2025
5	05/09.10.2025	29.05.2025	Almaspur	Yellareddypet-I	1 No.Buffalo belongs to Sri.Sonaveni Rajaiah S/o Narsaiah	40,000.00	due to Gale and wind the overhead LT lines fallen on buffalo	889849/ 10.10.2025
6	06/10.10.2025	15.05.2025	Kanagrthy	Konaraopet	1 No.Cow Belongs to Sri.Bade Samydas S/o Gundaiah	40,000.00	cow has touched its mouth to the Horn Gap arrester at the HT Bush of SS-XXIV 100 KVA DTR	889856/ 10.10.2025
7	07/27.10.2025	11.10.2024	Kolanoor	Konaraopet	Sri.Ponugoti Manohar Rao S/o Damodhar Rao	5,00,000.00	electric shock from the pump set starter while repairing it over the tractor tanker.	889894,95/30.10.2025
8	08/27.10.2025	22.05.2025	RR Colony Neelojipally	Boinpally	Smt.Yerra Shobha W/o Rajireddy	5,00,000.00	due to faulty internal open house wiring provided by the consumer	889892,93/30.10.2025
9	09/27.10.2025	25.05.2025	Bowsaipet	Konaraopet	Sri.Thikkala Jagan S/o Poshaiiah	7,000.00	the damaged service wire connected to the 3-Ph meter feeding GP water works bearing SC.No.40401 00827	889897/ 30.10.2025
10	10/27.10.2025	21.06.2025	Suddala	Konaraopet	1No.Buffalo belongs to Sri.Kudukala Lingaiah S/o Ellaiah	40,000.00	Due to heavy winds the LT phase and neutral of SS-VII/100 KVA were touched each other, thus both stay sets were conducting, came in contact	889898/ 30.10.2025
11	11/27.10.2025	27.05.2025	Nimmapally	Konaraopet	1 No.Buffalo & 1 No.Heifer belongs to Sri.Kusa Ram Reddy S/o Mallaiah	80,000.00	Due to heavy winds the LT line of SS-XXXVII 100 KVA DTR snapped .	889896/ 30.10.2025
12	12/27.10.2025	20.07.2025	Jaggaraopally	Boinpally	1No.Sheep belongs to Smt.Kondaveni Rajavva W/o Ravi	7,000.00	Due to damaged earth pipe	889899/ 30.10.2025
13	13/05.12.2025	27.02.2025	Musthabad	Musthabad	Sri.Ollepu Devaiah S/o Ramulu	5,00,000.00	came in contact with damaged service wire of service number 70702 03165 and was electrocuted.	890002,03/08.12.2025

Sanction No. & Date	Date of Accident	Village	Mandal/Operation section	Details of Victim (Human/Animal)	Sanction Amount in Rs.	Reason	cheque no./Date	
14	14/05.12.2025	15.10.2024	Kondapoor	Musthabad	1No.Buffalo belongs to Smt.Jella Chandrakala W/o Thulasidasu	40,000.00	buffalo has touched the illegally erected fence around farm land of Erikala Ganesh S/o Ramulu	890001/ 08.12.2025
15	15/05.12.2025	03.08.2025	Thangallapally	Thangallapally	1No.Buffalo belongs to Sri.Budidha Narsaiah S/o Venkataiah	40,000.00	got electrical shock as the cable from the starter to motor of GP water works well had a joint wire not insulated	890090/ 18.01.2026
16	16/05.12.2025	05.12.2025	Kolanoor	Konaraopet	1No.Cow belongs to Sri.Burra Ravinder S/o Parsharamulu	40,000.00	received electric shock by touching its mouth while standing on clay mound to the LT line.	890113/ 24.01.2026
17	17/01.01.2026	14.06.2025	Therlumaddi	Musthabad	Sri.Baithi Rajaiah S/o Mallaiah	5,00,000.00	came in contact with damaged internal house wiring of service number 70717 00214	890083,84/16.01.2026
18	18/30.01.2026	22.03.2025	Manuwada	Boinpally	Sri Dasari Narsaiah s/o Mallaiah	5,00,000.00	climbed drum stick tree with sickle tool, while cutting the branches,branches fell on the 6.3 kv line passing under the tree	890149,50/ 07.02.2026
19	19/30.01.2026	20.07.2025	Nimmapally	Konaraopet	Sri.Anumula Mahender s/o Lachireddy	5,00,000.00	accidentally cut the service wire carrying electricity with his grass weeding machine	890151,52/ 07.02.2026
20	20/30.01.2026	09.11.2025	Sthambampally	Boinpally	1 NO. Cow belongs to Sri.Muthyapu Parsharam s/o Hanmandlu	40,000.00	Lt pin insulator over the iron pole has failed and cow has came into contact with LG fault electrocuted	890148/ 07.02.2026
21	21/13-02-2026	27-08-2025	Bhukya Thanda	Veernapally	1 no. buffalo belongs to Smt. Guguloth Sakku	40,000.00	came in contact with damaged cable of street light	890188/ 18.02.2026
22	22/13-02-2026	17.01.2026	Lingampally	Vemulawada Rural	1 no. ox belongs to Sri Dumala Devaiah s/o Chinna Mallaiah	40,000.00	fell on the service wire of Agriculture motor starter box	890189/ 18.02.2026
23	23/13-02-2026	06.12.2024	Gundaram	Yellareddypet	3 no.s sheep & 3 no.s goats belong to Sri.Mudavath Bheem Singh s/o Ganava Navak	42,000.00	due to heavy gale & wind, insulator flashover occurred and fence round the animals came in contact with the 6.3 Kv line above	890190/ 18.02.2026
24	24/13.02.2026	10.12.2025	Chinthaltana	Thangallapally	1 no. buffalo belongs to Sri. Bhoopathi Mallaiah	40,000.00	touched the motor cable of GP water works well which is not properly insulated	890191/ 18.02.2026
25	25/13.02.2026	23.05.2025	Chandragiri	Vemulawada Urban	1 no. buffalo of owner Sri.Gundam Narsaiah	40,000.00	came in contact with iron rod which was used to tie the service wire(not properly insulated) coming from electric pole to nearby well	890192/ 18.02.2026
						41,63,000.00		

Bhoopathi

Managing Director
CESS LTD., SIRCILLA